




- WIRING INSTRUCTIONS— fail secure strike with one button



Depressing the push button would close the circuit, allow power to flow and release the strike.

Power Supply may be AC or DC, depending on the requirements of the strike.
In most cases AC power can be used intermittent (10 seconds or less). In most cases DC power can be used Continuous Duty (indefinite).
AC power will cause the strike to "buzz", DC power will "click".